




Наименование	Фото	Стоимость у.е.
<b>DIESEL-6/9</b>		<b>50</b>
<b>IVECO-30</b>		<b>35</b>
<b>IVECO-38</b>		<b>35</b>
<b>BENZ-14</b>		<b>35</b>
<b>VOLVO-8</b>		<b>35</b>
<b>ISUZU-3</b>		<b>35</b>
<b>ISUZU-20</b>		<b>35</b>
<b>HITACHI-4</b>		<b>35</b>

<p><b>HITACHI-6</b></p>	 <p>A black diagnostic cable with a Hitachi-6 connector on the left and a white connector on the right.</p>	<p><b>35</b></p>
<p><b>MAN-37</b></p>	 <p>A black diagnostic cable with a MAN-37 connector on the left and a large black cylindrical connector on the right.</p>	<p><b>35</b></p>
<p><b>DENSO-12</b></p>	 <p>A black diagnostic cable with a Denso-12 connector on the left and a white connector on the right.</p>	
<p><b>DIESEL-HY</b></p>	 <p>A black diagnostic connector with a 16-pin OBD-II port on the top and a 16-pin connector on the bottom.</p>	<p><b>30</b></p>
<p><b>CAT-9</b></p>	 <p>A black diagnostic cable with a CAT-9 connector on the left and a black connector on the right.</p>	<p><b>35</b></p>
<p><b>OBD-16</b></p>	 <p>A black diagnostic cable with an OBD-16 connector on the left and a black cylindrical connector on the right.</p>	<p><b>35</b></p>